Evidence closeout packet

Version 1 | Created 2026-10-21T12:00:00.000Z

Package: sample-packet

Project: SYNTHETIC solar closeout (sample-project)

Site address: Synthetic site; no real address

Workflow: residential-solar-closeout v1 / Residential Solar

Submitted by: Email not recorded (sample-installer)

Client submission time: 2026-10-21T12:00:00.000Z

Evidence images: 6

GPS reported by device: Missing

GPS status / exception: missing: GPS metadata was not captured.

Weather: Missing

Weather status / exception: missing: Weather metadata was not captured.

Review: Evidence version only. Approval and release are separate, dated records in the application. This packet does not assert approval.

Provenance: Client capture times, GPS and overlays are reported context. Hashes make the submitted record tamper-evident; they do not prove camera origin, location, or a utility/rebate outcome. AI QA is advisory.

Notes: SYNTHETIC DEMONSTRATION. Illustrations show packet layout, not actual equipment or verified work. Example correction: replace an unreadable inverter nameplate in a new full-checklist package. Internal approval and release are separate dated records. This packet does not certify compliance.

Package SHA-256: 05dddc6c175b8a90b53399568906040155b865981d687b0d7e90168cfbdfd64e

Previous chain hash: GENESIS_BLOCK

Pinned requirements

Service Panel Overview: Show the complete service panel and surrounding working area.

Source / verification: demonstration: Worksite Proof generic residential-solar-closeout v1

Reviewer / applicability: No external reviewer verified. Demonstration only; confirm this workflow against the customer requirement set before pilot admission.

Effective / reviewed: Not established / Not reviewed

Expected evidence: Show the complete service panel and surrounding working area.

Busbar and Main Breaker Ratings: Capture legible busbar and main-breaker ratings in one or more clear photos.

Source / verification: demonstration: Worksite Proof generic residential-solar-closeout v1

Reviewer / applicability: No external reviewer verified. Demonstration only; confirm this workflow against the customer requirement set before pilot admission.

Effective / reviewed: Not established / Not reviewed

Expected evidence: Capture legible busbar and main-breaker ratings in one or more clear photos.

Inverter Nameplate: Capture manufacturer, model, serial number, and electrical ratings.

Source / verification: demonstration: Worksite Proof generic residential-solar-closeout v1

Reviewer / applicability: No external reviewer verified. Demonstration only; confirm this workflow against the customer requirement set before pilot admission.

Effective / reviewed: Not established / Not reviewed

Expected evidence: Capture manufacturer, model, serial number, and electrical ratings.

Rapid Shutdown and Warning Labels: Show installed placards and warning labels in their final locations.

Source / verification: demonstration: Worksite Proof generic residential-solar-closeout v1

Reviewer / applicability: No external reviewer verified. Demonstration only; confirm this workflow against the customer requirement set before pilot admission.

Effective / reviewed: Not established / Not reviewed

Expected evidence: Show installed placards and warning labels in their final locations.

Array and Wiring Overview: Show the completed array, visible wiring methods, and equipment placement.

Source / verification: demonstration: Worksite Proof generic residential-solar-closeout v1

Reviewer / applicability: No external reviewer verified. Demonstration only; confirm this workflow against the customer requirement set before pilot admission.

Effective / reviewed: Not established / Not reviewed

Expected evidence: Show the completed array, visible wiring methods, and equipment placement.

Meter and Interconnection Point: Show the meter area and completed point of interconnection.

Source / verification: demonstration: Worksite Proof generic residential-solar-closeout v1

Reviewer / applicability: No external reviewer verified. Demonstration only; confirm this workflow against the customer requirement set before pilot admission.

Effective / reviewed: Not established / Not reviewed

Expected evidence: Show the meter area and completed point of interconnection.

Service Panel Overview

Requirement: service-panel-overview | Photo: sample-photo-1



Client capture time: 2026-10-21T12:00:00.000Z
Capture source: library
Server receipt context: Not recorded
Server bytes verified: Historical upload; verification not recorded
AI QA (advisory): unchecked: No result
Submitted prepared image SHA-256: fb465887af0cd67128f273680295151697baaacda86ec05cca66a5b0935dbb11
Storage object generation: Historical upload; not pinned

Busbar and Main Breaker Ratings

Requirement: busbar-main-breaker | Photo: sample-photo-2



Client capture time: 2026-10-21T12:00:00.000Z
Capture source: library
Server receipt context: Not recorded
Server bytes verified: Historical upload; verification not recorded
AI QA (advisory): unchecked: No result
Submitted prepared image SHA-256: e37ed4f3371f41d25066db91817528feb8b2a222d6847cc3b96f266c3e5287e5
Storage object generation: Historical upload; not pinned

Inverter Nameplate

Requirement: inverter-nameplate | Photo: sample-photo-3



Client capture time: 2026-10-21T12:00:00.000Z
Capture source: library
Server receipt context: Not recorded
Server bytes verified: Historical upload; verification not recorded
AI QA (advisory): unchecked: No result
Submitted prepared image SHA-256: 85fa8ccdf62767294dd6c6329aa2b0f9c5d7f2c760fedbe4ffc0bc2d0540e42e
Storage object generation: Historical upload; not pinned

Rapid Shutdown and Warning Labels

Requirement: rapid-shutdown-labels | Photo: sample-photo-4



Client capture time: 2026-10-21T12:00:00.000Z
Capture source: library
Server receipt context: Not recorded
Server bytes verified: Historical upload; verification not recorded
AI QA (advisory): unchecked: No result
Submitted prepared image SHA-256: 42dbae666b2e499304f341c7e938d1f4541b7c7f413025f2d4498970156deea5
Storage object generation: Historical upload; not pinned

Array and Wiring Overview

Requirement: array-wiring-overview | Photo: sample-photo-5



Client capture time: 2026-10-21T12:00:00.000Z
Capture source: library
Server receipt context: Not recorded
Server bytes verified: Historical upload; verification not recorded
AI QA (advisory): unchecked: No result
Submitted prepared image SHA-256: dcdf89f972e40c066c288a4c8d61d0ade4691db5149a8f73d23d2478a0a6e749
Storage object generation: Historical upload; not pinned

Meter and Interconnection Point

Requirement: meter-interconnection | Photo: sample-photo-6



Client capture time: 2026-10-21T12:00:00.000Z
Capture source: library
Server receipt context: Not recorded
Server bytes verified: Historical upload; verification not recorded
AI QA (advisory): unchecked: No result
Submitted prepared image SHA-256: 53dfa56ad99613d381be17a8dacd329d7275a65d53337f4e04a61c0566c3448f
Storage object generation: Historical upload; not pinned